

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program August 9, 2011

Reviewed:	R
	IC

Mine Name: Black Magic	Permit Number: S/023/0108	
Operator Name: Metamining of Utah	Inspection Date: August 3, 2011	
Inspector(s): Jerry Mansfield BLM, Wayne Western DOGM	Time: 12:40 – 1:05 PM	
Other Participants: None	Mine Status: Rec	

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Re-vegetation			
11.	Air Quality			
12.	Other			

#### **Purpose of Inspection:**

This was a bond release inspection in conjunction with the BLM

### **Inspection Summary:**

The Permittee has a bond on the project for \$8,400.00 held by the Division in a cash account.

According to the annual report the site was mined in 2010. Mining consisted or removal of waste/ore piles. The areas was scarified on April 6, 2010 and seeded on September 18, 2010.

Because mining occurred on waste/ore piles there were no shafts, adits or highwalls on site. The site is near the Black Boy Mine that does have shafts, adits and highwalls. AML was notified of those features.

All trash had been removed and there was no deleterious material on site.

There were no road on the site, access was from a public road to the mine site.

Drainage is controlled by vegetation and proper grading.

Inspection Date: August 3, 2011

Page 2 of 4 S/023/0108

There was no salvaged topsoil pile when the site had been disturbed.

There are no impoundments at the site.

#### **Conclusions and Recommendations:**

The site be granted Phase I bond release. \$2,000 be keep to assure revegetative success. Since the area where the mine was located, has very little desireable vegetation, the Division will decide in a year, if revegetation work has been completed within satisfactory limits or if reseeding will enhance the chance of revegetative success.

Inspector's Signature hape The

WHW:

cc: (OPERATOR)

Jerry Mansfield@BLM.gov


O:\M023-Juab\S0230108-BlackMagic\inspections\INSP-08032011rev.doc



Looking South



Looking East



Close up of vegetation



Before picture 10/06/2009